

BORDEN PARISH HALL REPORT OCTOBER 22

1. The outside security lights from the car park to the side door have been repaired, and are working correctly;
2. The handrails at the side and rear doors of the hall have been checked and tightened where required;
3. The number of users booking the hall is steadily increasing, and vacant slots are now becoming rare.

John Hepburn
Chairman Borden Parish Hall